

For replacement parts information or an application guide, visit our website at www.hubbell-icd.com or contact your local Hubbell sales office.

## Replacement Parts

November 2003

## IMPORTANT

THESE INSTRUCTIONS DO NOT PURPORT TO COVER ALL DETAILS OR VARIATIONS IN EQUIPMENT, NORTO PROVIDE FOR EVERY POSSIBLE CONTINCENCY TO BE MET IN CONNECTION WITH INSTALLATION, OPERATION OR MAINTENANCE. SHOULD FURTHER INFORMATION BE DESIRED OR SHOULD PARTICULAR PROBLEMS ARISE WHICH ARE NOT COVERED SUPFICIENTLY FOR THE PURCHASER'S PURPOSES, THE M ATTER SH OULD BE REFERRED TO THE LOCAL HUBBELL SALES OFFICE.

58-GA14


Rever sing OFF ON Two Speed Special Purpose Class 58 A14, A15




## **AWARNING**


Hazardous voltage. Can cause death or serious injury

Disconnect main power and control voltages before installation or maintenance on this equipment.





A14 (Interchanging Leads To 2 And 4 Reverses Motor Rotation)					
Direct Current 1/4 HP 115-230V	AC Single and Three Phase 1 HP 110-550V				
D.C. Shunt	Condenser Motor 4 Leads	Three Phase	Repulsion Induction Motor, 4 Leads, Series Winding Reversing Type Only		
D.C. Series	Condenser Motor 6 Leads 120V	Split Phase	Repulsion-Induction Three Motor Leads		
D.C. Compound	Condenser Motor 6 Leads 240V	OFF - ON DPST  A b o o d o o d o o d o o d o o d o o d o o d o o d o o d o o d o o d o o o d o o o o o o o o o o o o o o o o o o o o	Internal Connections Bottom View  A T T T T T T T T T T T T T T T T T T		



Item	Part Name	Part number
Α	Molded Base Assembly Complete with (6) Fingers (Qty. 1)	D09593001
В	Top (A14) (Qty. 1)	D03519001
	Top (A15) (Qty. 1)	D30519002
С	Spindle (Qty. 1)	D27655001
D	Radial Handle (S tandard) (Qty. 1)	D55 711001
	Sa fety Handle (Optional, not shown) (Q ty. 1)	D10018001

NOTE: When ordering replacement parts, give catalog number of control and part name and number

(For Engineering Reference Only - Rev. C)